

臺北縣 河川水質監測結果

中華民國 95 年 10 月

河川名稱	監測站名	監測站編號	水體分類等級	採樣日期	採樣時間	氣溫 ℃	水流量 CMS	水質紀錄											水質紀錄											備註				
								水溫 ℃	pH值	溶氧量 mg/L	總氮 mg/L	總磷 mg/L	生化需氧量 (5天20℃) mg/L	化學需氧量 mg/L	懸浮固體 mg/L	鎘	鉛	總鉻	汞	銅	鋅	導電度 μmho/cm/25℃	大腸桿菌群 個/100ml	陰離子表面活性劑 mg/L	氨氮 mg/L	氯鹽 mg/L	透視度 cm	濁度 NTU	六價鉻 mg/L(第四位)		硫酸鹽 mg/L	鐵 mg/L	錳 mg/L	
																																		mg/L(統計至小數第四位)
水仙溪	靈山宮	R01	無	10/11	10:15	25.8		25.5	7.5	3.6			11	39	6.6								203	6.0*10 ²		0.06	10	9.0	55		28			
水仙溪	小石板橋	R02	無	10/11	10:30	26.5		25.5	7.8	5.4			16	38	21								201	7.4*10 ²		0.006	12	>30	2.1		25			
林口溪	林口溪橋	R03	無	10/11	11:00	26.7		27.7	7.7	5.4			19	50	10								179	7.1*10 ²	N.D<0.005	8.6	>30	3.5						
林口溪	下福橋	R04	無	10/11	11:12	27.7		29.6	8.0	8.6			12	32	8.7								149	5.7*10 ²	N.D<0.005	14	>30	0.85						
觀音坑溪	集福橋	R05	無	10/12	09:35	27.9		27.7	8.4	3.2			170	322	38								104	6.9*10 ³		0.02	30	>30	2.1		11			
觀音坑溪	觀音坑三號橋	R06	無	10/12	09:43	27.9		25.6	7.7	8.4			9.0	24	10								119	2.4*10 ³		0.007	38	>30	0.85		9.0			
五股坑溪	洲子一橋	R07	無	10/12	10:01	27.5		25.7	7.7	4.0			36	107	22								179	7.8*10 ³		0.07	38	>30	1.8					
五股坑溪	俊成橋	R08	無	10/12	10:05	27.3		25.8	7.2	2.2			37	147	28								863	3.9*10 ⁴		0.28	228	>30	1.8					
大科坑溪	大窠橋	R09	無	10/12	10:15	27.9		26.7	7.9	6.4			14	91	16								124	3.1*10 ³	N.D<0.005	34	>30	1.6		12				
大科坑溪	山腳溪橋	R10	無	10/12	10:25	27.5		26.8	7.8	7.7			8.5	69	11								197	1.0*10 ⁴		0.02	34	>30	2.0		18			
新店溪	青潭堰取水口	R11	甲	10/18	10:15	24.8		23.2	7.3	8.9		N.D<0.003	N.D<1.0	N.D<3.0	N.D<2.5							144	3.9*10 ³		0.04	20	>30	2.3		35				
新店溪	直潭堰取水口	R12	甲	10/18	10:30	25.4		25.2	6.9	8.4		0.008	N.D<1.0	N.D<3.0	N.D<2.5							105	2.7*10 ²		0.01	25	>30	0.90		13				
大漢溪	鳶山堰取水口	R13	乙	10/17	10:10	28.6		25.3	8.0	8.3		0.06	N.D<1.0	6.7	33								203	6.0*10 ²		0.06	10	9.0	55		28			
三峽河	三峽堰取水口	R14	無	10/17	10:30	25.9		24.7	8.2	8.8		0.005	N.D<1.0	5.2	N.D<2.5								201	7.4*10 ²		0.006	12	>30	2.1		25			
大豹溪	湊合橋	R17	無	10/17	10:45	24.6		23.8	8.2	9.0			N.D<1.0	3.5	N.D<2.5								179	7.1*10 ²	N.D<0.005	8.6	>30	3.5						
大豹溪	東眼橋	R18	無	10/17	11:00	24.5		23.7	8.2	9.0			N.D<1.0	3.0	N.D<2.5								149	5.7*10 ²	N.D<0.005	14	>30	0.85						
瑪鋸溪	瑪鋸溪取水口	R21	無	10/24	10:45	22.1		22.0	7.4	9.1		0.05	N.D<1.0	N.D<3.0	3.1								104	6.9*10 ³		0.02	30	>30	2.1		11			
瑪鋸溪	裕大橋	R22	無	10/24	10:30	20.9		21.2	7.6	9.0		0.04	N.D<1.0	3.7	N.D<2.5								119	2.4*10 ³		0.007	38	>30	0.85		9.0			
瑪鋸溪	四十九號橋	R23	無	10/24	10:05	23.1		22.1	7.0	8.8			1.3	4.2	3.1								179	7.8*10 ³		0.07	38	>30	1.8					
瑪鋸溪	國中橋	R24	無	10/24	10:10	23.1		20.5	7.0	7.3			1.5	6.0	2.7								863	3.9*10 ⁴		0.28	228	>30	1.8					
東勢格溪	東勢格溪取水口	R31	無	10/25	11:00	23.5		22.3	7.2	9.1		0.04	N.D<1.0	N.D<3.0	6.6								124	3.1*10 ³	N.D<0.005	34	>30	1.6		12				
景美溪	石碇取水口	R32	無	10/25	11:26	23.1		22.8	7.9	9.0		0.10	1.3	N.D<3.0	2.8								197	1.0*10 ⁴		0.02	34	>30	2.0		18			
基隆河	圓山取水口	R33	乙	10/31	10:45	22.1		21.4	7.2	8.5		0.03	N.D<1.0	N.D<3.0	6.6								144	3.9*10 ³		0.04	20	>30	2.3		35			
基隆河	康誥坑溪取水口	R34	無	10/31	10:20	24.0		21.8	7.4	8.9		0.04	N.D<1.0	N.D<3.0	2.8								105	2.7*10 ²		0.01	25	>30	0.90		13			