

公開類
季報

期間終了一個月內編報

新北市 河川水質監測結果

中華民國100年9月

編製機關 新北市政府環境保護局
表號 1134-05-02-2

河川名稱	監測站名	監測站編號	水體分類等級	採樣日期	採樣時間	氣溫 ℃	水流量 CMS	水質紀錄							水質紀錄										備註										
								水溫 ℃	pH值	溶氧量 mg/L	總氮 mg/L	總磷 mg/L	生化需氧量 (5天20℃) mg/L	化學需氧量 mg/L	懸浮固體 mg/L	鎘	鉛	總銻	汞	銅	鋅	導電度 μmho/ cm/25℃	大腸桿菌 群 個/100mL	陰離子 表面活性劑 mg/L		氨氮 mg/L	氯鹽 mg/L	透視度 cm	濁度 NTU	六價 鉻 mg/L (第四位)	硫酸 鹽 mg/L	鐵 mg/L	錳 mg/L		
																																		mg/L(統計至小數第四位)	
水仙溪	靈山宮	R01	無	9/6	09:55	24.2		24.5	7.4	5.8			2.8	12.5	N.D.<2.5									298	2.80*10 ⁴		3.11	27	>30	1.1					
水仙溪	小石板橋	R02	無	9/6	09:47	24.5		26.1	7.1	6.3			4.3	24.0	8.8									442	3.60*10 ⁵		3.41	40	>30	6.2					
林口溪	林口溪橋	R03	無	9/6	10:19	21.5		25.1	7.8	6.5			11.6	72.1	482									593	4.20*10 ⁵		11.5	77	3	400					
林口溪	下福橋	R04	無	9/6	10:30	24.4		25.9	8.1	8.7			5.2	27.5	19.1									547	3.10*10 ⁴		2.64	81	>30	7.1					
觀音坑溪	集福橋	R05	無	9/7	09:36	26.8		27.1	8.3	8.2			12.1	80.5	22.7									1220	6.00*10 ⁴		8.57	83	20	11					
觀音坑溪	觀音坑三號橋	R06	無	9/7	09:27	27.8		27.3	7.3	7.8			8.5	36.3	13.0									484	1.40*10 ⁵		0.46	63	15	50					
五股坑溪	洲子一橋	R07	無	9/7	09:50	25.6		27.4	7.8	7.0			16.2	58.0	16.6									532	4.60*10 ⁵		8.4	48	>30	21					
五股坑溪	俊成橋	R08	無	9/7	10:00	25.8		27.8	7.5	6.2			14.5	66.9	27.5									529	3.10*10 ⁵		6.29	44	20	37					
大科坑溪	大窠橋	R09	無	9/7	10:15	25.1		27.2	8.2	8.7			18	43.5	128									1300	6.60*10 ⁵		12.9	235	17	12					
大科坑溪	山腳溪橋	R10	無	9/7	10:25	27.9		28.6	7.9	5.4			12.1	51.6	7.0									1410	2.90*10 ⁵		11.4	240	23	14					
新店溪	青潭堰取水口	R11	甲	9/13	09:52	25.5		25.3	7.6	8.3		0.06	1.7	12.1	182									99	3.40*10 ³		0.02	4.6	4.5	180				11.4	
新店溪	直潭堰取水口	R12	甲	9/13	10:10	25.6		24.2	7.4	8.4		0.01	N.D.<0.6	7.3	5.8									89	2.40*10 ³		0.009	6.3	>30	9.4				10.2	
大漢溪	鳶山堰取水口	R13	乙	9/14	10:00	25.8		26.1	7.1	6.5		0.05	0.7	8.2	34.6									223	7.00*10 ²		0.14	4.6	13.9	40				32.8	
三峽河	三峽堰取水口	R14	無	9/14	10:20	26.4		26.2	7.2	8.7		0.02	N.D.<0.6	8.2	N.D.<2.5									167	4.10*10 ³		0.03	4.9	>30	3.1				18.5	
大豹溪	竹崙橋	R15	無	9/14	10:50	26.5		26.8	7.2	8.8			N.D.<0.6	10.2	2.8	0.001	N.D.<0.015	N.D.<0.002		N.D.<0.002	0.016			135	6.60*10 ³		0.04	6.6	>30	1.7			0.056	0.004	
大豹溪	橫溪橋	R16	無	9/14	11:10	27.2		26.6	7.3	8.7			1.4	8.2	2.6	0.001	N.D.<0.015	N.D.<0.002		0.002	0.008			178	4.00*10 ⁴		0.23	8.8	>30	3.1			0.07	0.017	
瑪鍊溪	梅竹橋	R19	甲	9/20	10:26	23.1		23.2	7.0	8.0		0.05	N.D.<0.6	9.4	7.3	0.001	N.D.<0.015	N.D.<0.002		N.D.<0.002	0.017			128	7.90*10 ²		0.08	11	>30	8.0			2.0	0.157	0.031
瑪鍊溪	雙溪取水口	R20	甲	9/20	10:42	22.0		23.2	6.6	6.8		0.02	N.D.<0.6	N.D.<3.6	4.1	0.001	N.D.<0.015	N.D.<0.002		N.D.<0.002	0.020			132	1.10*10 ⁴		0.09	12	>30	5.0			13.4	0.132	0.026
瑪鍊溪	老梅溪取水口	R25	無	9/21	10:13	19.6		20.0	6.6	8.7		0.04	N.D.<0.6	N.D.<3.6	3.0	N.D.<0.0006	0.018	N.D.<0.002		N.D.<0.002	0.008			108	7.80*10 ³		0.01	13	>30	3.6			3.1	0.059	0.004
瑪鍊溪	大溪墘橋	R26	無	9/21	10:22	19.5		21.2	6.7	8.9			N.D.<0.6	3.8	9.6	N.D.<0.0006	N.D.<0.015	N.D.<0.002		N.D.<0.002	0.011			134	6.90*10 ³		0.02	11	>30	5.7			0.137	0.012	
東勢格溪	二十三號橋	R27	無	9/21	10:30	20.1		21.7	6.6	7.4			1.2	6.1	3.1	N.D.<0.0006	N.D.<0.015	N.D.<0.002		N.D.<0.002	0.010			1220	5.30*10 ⁴		0.08	334	>30	2.8			0.124	0.034	
景美溪	百拉卡取水口	R28	無	9/27	11:00	21.1		19.2	7.0	8.7		0.08	1.2	N.D.<3.6	7.7	0.001	0.017	N.D.<0.002		N.D.<0.002	0.012			108	6.20*10 ³		0.02	9.8	>30	2.5			5.1	0.047	0.003
基隆河	中和橋	R29	無	9/27	10:10	23.1		23.2	6.8	8.3			N.D.<0.6	N.D.<3.6	9.7	0.001	N.D.<0.015	N.D.<0.002		N.D.<0.002	0.016			154	2.80*10 ⁴		0.03	14	>30	5.9			0.276	0.024	
基隆河	第十號橋	R30	無	9/27	09:55	24.5		24.9	6.4	7.6			0.8	5.8	10.5	N.D.<0.0006	0.019	N.D.<0.002		N.D.<0.002	0.011			180	2.90*10 ⁴		0.06	21	>30	100			0.670	0.019	