

公開類
季報

期間終了一個月內編報

新北市 河川水質監測結果

中華民國100年10月

編製機關 新北市政府環境保護局
表號 1134-05-02-2

河川名稱	監測站名	監測站編號	水體分類等級	採樣日期	採樣時間	氣溫 ℃	水流量 CMS	水質紀錄							水質紀錄										備註										
								水溫 ℃	pH值	溶氧量 mg/L	總氮 mg/L	總磷 mg/L	生化需氧量 (5天20℃) mg/L	化學需氧量 mg/L	懸浮固體 mg/L	鎘	鉛	總銻	汞	銅	鋅	導電度 μmho/ cm/25℃	大腸桿菌 群 個/100mL	陰離子 界面 活性劑 mg/L		氨氮 mg/L	氯鹽 mg/L	透視度 cm	濁度 NTU	六價 鉻 mg/L (第四位)	硫酸 鹽 mg/L	鐵 mg/L	錳 mg/L		
																																		mg/L(統計至小數第四位)	
水仙溪	靈山宮	R01	無	10/4	10:00	19.8		21.7	6.7	6.2			3.1	15.8	7.6									260	3.80*10 ⁴		3.04	20	>30	3.5					
水仙溪	小石板橋	R02	無	10/4	09:50	19.2		21.0	6.7	7.0			6.0	27.7	7.0									342	4.10*10 ⁵		4.47	30	>30	4.9					
林口溪	林口溪橋	R03	無	10/4	10:20	17.0		19.7	6.9	7.8			7.3	48.9	16.2									350	4.20*10 ⁴		6.12	35	>30	13					
林口溪	下福橋	R04	無	10/4	10:35	18.0		20.6	6.9	7.8			8.3	34.1	22.0									358	6.70*10 ⁴		2.77	39	>30	14					
觀音坑溪	集福橋	R05	無	10/5	09:33	23.6		23.9	7.1	6.2			5.8	53.7	5.0									1390	3.00*10 ⁶		10.8	105	>30	13					
觀音坑溪	觀音坑三號橋	R06	無	10/5	09:41	23.3		23.0	6.7	7.8			1.5	13.2	7.1									405	3.40*10 ⁴		0.4	50	>30	19					
五股坑溪	洲子一橋	R07	無	10/5	09:55	22.6		23.1	6.8	3.4			13.2	48.7	17.2									457	1.20*10 ⁷		8.68	37	>30	15					
五股坑溪	俊成橋	R08	無	10/5	10:05	23.3		23.3	6.8	6.3			3.4	38.5	12.7									725	1.70*10 ⁵		4.67	140	>30	17					
大科坑溪	大窠橋	R09	無	10/5	10:17	22.9		23.3	7.1	6.3			8.5	39.3	4.4									1170	5.80*10 ⁶		14.9	224	25	16					
大科坑溪	山脚溪橋	R10	無	10/5	10:25	23.7		23.7	7.0	7.3			5.0	26.0	N.D.<2.5									1250	2.20*10 ⁵		13.8	247	>30	7.4					
新店溪	青潭堰取水口	R11	甲	10/11	09:55	26.1		22.4	6.8	8.8			0.05	N.D.<0.6	4.4	65.3								77	7.10*10 ³		0.05	7.0	8.0	60			11.1		
新店溪	直潭堰取水口	R12	甲	10/11	10:20	24.6		23.7	6.6	9.0			0.04	N.D.<0.6	13.6	47.0								78	4.40*10 ³		0.04	8.6	10.2	60			10.3		
大漢溪	鳶山堰取水口	R13	乙	10/12	10:00	27.1		25.8	6.8	7.9			0.05	2.8	10.1	47.3								205	1.30*10 ⁴		0.19	5.1	10.0	80			30.1		
三峡河	三峡堰取水口	R14	無	10/12	10:20	25.6		23.3	7.4	8.8			0.06	N.D.<0.6	N.D.<3.6	3.0								145	2.10*10 ⁴		0.01	5.2	>30	4.4			17.8		
大豹溪	湊合橋	R17	無	10/12	10:30	24.7		23.4	7.4	8.8			N.D.<0.6	4.4	N.D.<2.5									135	1.20*10 ⁴		N.D.<0.005	5.5	>30	2.2					
大豹溪	東眼橋	R18	無	10/12	10:35	25.3		22.7	7.3	8.8			N.D.<0.6	6.6	3.2									116	9.40*10 ³		0.006	5.0	>30	2.8					
瑪鍊溪	瑪鍊溪取水口	R21	無	10/19	10:45	24.1		23.5	6.8	8.9			0.04	N.D.<0.6	8.3	N.D.<2.5								129	7.90*10 ³		0.009	13	>30	2.2			10.3		
瑪鍊溪	裕大橋	R22	無	10/19	10:30	24.1		23.1	6.8	9.0			0.05	N.D.<0.6	N.D.<3.6	2.9								101	5.10*10 ³		0.006	14	>30	2.0			7.6		
瑪鍊溪	四十九號橋	R23	無	10/19	09:50	24.2		23.8	6.6	9.0			N.D.<0.6	8.5	N.D.<2.5									139	6.90*10 ³		0.02	14	>30	3.7					
瑪鍊溪	國中橋	R24	無	10/19	10:10	25.0		24.2	6.7	9.0			N.D.<0.6	10.0	N.D.<2.5									156	1.80*10 ⁴		0.09	14	>30	3.0					
東勢格溪	東勢格溪取水口	R31	無	10/25	10:30	21.2		20.4	6.4	8.9			0.03	N.D.<0.6	5.4	5.4								97	4.80*10 ⁴		0.04	7.3	>30	5.4			8.3		
景美溪	石碇取水口	R32	無	10/25	10:00	24.4		22.4	6.6	8.8			0.13	1.1	7.3	7.1								138	4.80*10 ⁴		0.06	7.1	>30	5.5			9.4		
基隆河	圓山取水口	R33	乙	10/26	10:30	17.0		19.0	6.9	9.0			0.02	N.D.<0.6	N.D.<3.6	5.8								124	9.60*10 ³		0.02	8.5	>30	9.1			10.0		
基隆河	康誥坑溪取水口	R34	無	10/26	10:00	20.5		19.7	6.9	9.0			0.03	N.D.<0.6	8.9	N.D.<2.5								88	5.30*10 ³		0.03	9.4	>30	2.8			21.4		