

公開類
季報

期間終了一個月內編報

新北市 河川水質監測結果

中華民國101年10月

編製機關 新北市政府環境保護局
表號 1134-05-02-2

河川名稱	監測站名	監測站編號	水體分類等級	採樣日期	採樣時間	氣溫 ℃	水流量 CMS	水質紀錄										水質紀錄										備註								
								水溫 ℃	pH值	溶氧量 mg/L	總氮 mg/L	總磷 mg/L	生化需氧量 (5天20℃) mg/L	化學需氧量 mg/L	懸浮固體 mg/L	鎘	鉛	總鎳	汞	銅	鋅	導電度 μmho/cm/25℃	大腸桿菌群 個/100mL	陰離子表面活性劑 mg/L	氨氮 mg/L	氯鹽 mg/L	透視度 cm		濁度 NTU	六價鉻 mg/L(統計第四位)	硫酸鹽 mg/L	鐵 mg/L	錳 mg/L			
																																		mg/L(統計至小數第四位)		
水仙溪	靈山宮	R01	無	10/2	09:45	24		22.8	7.3	6.7			9.5	13.2	4.7										328	3.00*10 ³		7.99	28	>30	3.2					
水仙溪	小石板橋	R02	無	10/2	09:55	23.6		24.9	7.7	6.7			13.6	22	12.3										566	1.10*10 ⁴		22.7	48	>30.00	13					
林口溪	林口溪橋	R03	無	10/2	10:25	26.5		24	7.6	6.2			12.6	39.4	10										539	3.70*10 ⁴		8.8	76	>30	9.2					
林口溪	下福橋	R04	無	10/2	10:35	26.9		25.5	7.9	8.4			13.5	20.1	21.9										464	2.40*10 ⁴		2.88	62	>30	11					
觀音坑溪	集福橋	R05	無	10/3	09:25	24.8		25	7.8	7.1			12.7	34.6	11										433	6.90*10 ⁵		2.26	47	>30.00	17					
觀音坑溪	觀音坑三號橋	R06	無	10/3	09:35	26.9		24.7	7.1	8.8			3.6	14.3	11.3										386	5.90*10 ⁴		0.36	46	20	11					
五股坑溪	洲子一橋	R07	無	10/3	09:50	26.4		25.4	7.2	5.4			38.5	78.7	43.4										446	5.60*10 ⁵		5.19	62	15	24					
五股坑溪	俊成橋	R08	無	10/3	10:00	29.4		26	7.5	6.4			19.2	64	29										453	2.40*10 ⁵		11.4	44	18	14					
大科坑溪	大窠橋	R09	無	10/3	10:17	28.2		26.1	7.7	7.2			14.2	45.8	19.2										1370	6.40*10 ⁵		9.41	207	24.5	17					
大科坑溪	山腳溪橋	R10	無	10/3	10:25	26.7		26.5	7.5	6.3			14.4	53	18.1										1250	4.20*10 ⁵		5.01	202	>30	16					
新店溪	青潭堰取水口	R11	甲	10/11	09:55	23		21.7	7.3	8.9		0.06	N.D.<0.6	3.5	90.7										113	5.60*10 ³		0.03	3.7	18	65		16			
新店溪	直潭堰取水口	R12	甲	10/11	10:10	20.4		21.9	7.6	8.5		0.02	N.D.<0.6	N.D.<3.1	7.5										78	1.00*10 ³		0.03	3.2	>30.00	13		11.1			
大漢溪	鳶山堰取水口	R13	乙	10/16	09:50	24.9		23.6	7.9	8.7		0.01	1.7	5.2	8.5										230	8.70*10 ²		0.05	3.9	>30.00	10		35.6			
三峽河	三峽堰取水口	R14	無	10/16	10:15	24		22.2	8.1	8.9		0.02	N.D.<0.6	3.5	N.D.<2.5										186	2.30*10 ³		0.04	3.8	>30.00	2.2		28.8			
大豹溪	湊合橋	R17	無	10/16	10:25	23.4		21.1	8.2	8.7			N.D.<0.6	N.D.<3.1	2.5										172	3.10*10 ³		0.02	3.5	>30.00	1.4					
大豹溪	東眼橋	R18	無	10/16	10:40	25.1		21.8	8.3	8.5			N.D.<0.6	N.D.<3.1	N.D.<2.5										145	5.30*10 ³		0.02	3.6	>30.00	0.9					
瑪鍊溪	瑪鍊溪取水口	R21	無	10/17	10:25	21.5		21.6	8.1	8.7		0.04	N.D.<0.6	N.D.<3.1	N.D.<2.5										113	2.40*10 ³		0.02	11	>30.00	2.4		7.4			
瑪鍊溪	裕大橋	R22	無	10/17	10:40	21.7		22.5	8.1	8.6		0.03	N.D.<0.6	N.D.<3.1	N.D.<2.5										149	1.60*10 ³		0.02	11	>30.00	2.2		10.3			
瑪鍊溪	四十九號橋	R23	無	10/17	10:00	21.4		22.7	8.3	8.8			N.D.<0.6	N.D.<3.1	3.1										158	4.10*10 ³		0.04	12	>30.00	2.0					
瑪鍊溪	國中橋	R24	無	10/17	10:10	21.7		23.1	7.4	7.1			N.D.<0.6	14.0	6.2										531	5.10*10 ⁴		0.21	108	>30.00	2.6					
東勢格溪	東勢格溪取水口	R31	無	10/24	10:30	24.6		21.2	7.3	9.0		0.04	N.D.<0.6	4.2	4										117	4.00*10 ³		0.02	8.6	>30.00	3.4		10.7			
景美溪	石碇取水口	R32	無	10/24	10:15	25.9		23.2	7.1	8.9		0.05	N.D.<0.6	4.0	N.D.<2.5										202	2.20*10 ³		0.03	8.1	>30.00	2.7		18.3			
基隆河	圓山取水口	R33	乙	10/25	10:30	25		23.4	7.9	9.0		0.02	0.8	3.3	N.D.<2.5										252	2.00*10 ²		0.01	9.4	>30.00	1.7		37.7			
基隆河	康諾坑溪取水口	R34	無	10/25	09:53	24.5		23.2	7.3	8.9		0.04	N.D.<0.6	N.D.<3.1	N.D.<2.5										143	1.20*10 ³		0.01	9.0	>30.00	1.1		10.4			