

公開類
季報

期間終了一個月內編報

新北市 河川水質監測結果

中華民國102年7月

編製機關 新北市政府環境保護局

表號 1134-05-02-2

河川名稱	監測站名	監測站編號	水體分類等級	採樣日期	採樣時間	氣溫 ℃	水流量 CMS	水質紀錄										水質紀錄										備註								
								水溫 ℃	pH值	溶氧量 mg/L	總氮 mg/L	總磷 mg/L	生化需氧量 (5天20℃) mg/L	化學需氧量 mg/L	懸浮固體 mg/L	鎘	鉛	總銻	汞	銅	鋅	導電度 μmho/ cm/25℃	大腸桿菌 群 個/100mL	陰離子 表面活性劑 mg/L	氨氮 mg/L	氯鹽 mg/L	透視度 cm		濁度 NTU	六價 鉻 mg/L (第四位)	硫酸 鹽 mg/L	鐵 mg/L	錳 mg/L			
																																		mg/L(統計至小數第四位)		
水仙溪	靈山宮	R01	無	7/2	10:35	33.5		28.5	7.5	5.2			6.6	11.9	N.D.<2.5									324	2.70*10 ³		6.92	21.8	>30	3.2						
水仙溪	小石板橋	R02	無	7/2	10:30	34.4		29.4	7.7	4.6			20.0	24.7	5.3									493	2.40*10 ⁵		15.8	34.3	>30	6.3						
林口溪	林口溪橋	R03	無	7/2	10:00	35.1		30.1	7.9	4.0			23.4	81.0	18.1									587	3.50*10 ⁴		16.1	61.9	>30	27						
林口溪	下福橋	R04	無	7/2	09:47	37.4		32.4	9.1	8.2			11.7	26.0	20.7									404	2.70*10 ⁴		0.59	90.7	>30	12						
觀音坑溪	集福橋	R05	無	7/3	09:25	31.5		30.8	8.4	9.2			8.0	36.7	11.8									1250	2.00*10 ⁵		3.69	130	>30	11						
觀音坑溪	觀音坑三號橋	R06	無	7/3	09:35	31.6		29.9	7.9	7.8			3.0	14.3	5.8									374	6.60*10 ⁴		0.24	28.3	>30	9.8						
五股坑溪	洲子一橋	R07	無	7/3	09:50	30.2		29.6	7.8	5.8			16.7	36.8	10.4									419	2.90*10 ⁵		5.13	33.5	>30	14						
五股坑溪	俊成橋	R08	無	7/3	10:00	31.4		30.6	7.9	9.0			7.7	29.4	8.1									410	2.20*10 ⁵		4.62	37.5	>30	11						
大科坑溪	大窠橋	R09	無	7/3	10:17	33.2		31.9	8.2	7.4			18.1	56.5	13.7									1300	5.50*10 ⁵		9.99	240	>30	8.4						
大科坑溪	山脚溪橋	R10	無	7/3	10:25	34.4		31.7	8.4	9.2			6.1	23.2	5.6									1410	8.40*10 ⁴		8.71	287	>30	5.0						
新店溪	青潭堰取水口	R11	甲	7/9	09:50	28.6		26.1	7.7	8.9		0.042	N.D.<0.8	4.1	84.8									8.1	5.60*10 ³		0.03	3.6	7.2	95			14.0			
新店溪	直潭堰取水口	R12	甲	7/9	10:10	29.0		26.5	7.5	8.1		0.030	N.D.<0.8	3.3	31.0									102	3.90*10 ³		0.03	3.1	16.0	55			13.6			
大漢溪	鳶山堰取水口	R13	乙	7/16	10:00	27.7		24.9	8.2	8.3		0.089	N.D.<0.8	40.4	1580									195	5.00*10 ³		0.04	5.5	0.7	550			25.1			
三峡河	三峡堰取水口	R14	無	7/16	10:28	8.5		24.4	8.1	8.5		0.041	N.D.<0.8	N.D.<3.1	21.6									123	2.30*10 ⁴		0.02	2.4	>30	21			12.5			
大豹溪	湊合橋	R17	無	7/16	11:10	30.0		26.6	8.2	8.4			N.D.<0.8	N.D.<3.1	N.D.<2.5	0.002	0.026	0.004						107	2.20*10 ⁴		0.04	3.5	>30	2.5						
大豹溪	東眼橋	R18	無	7/16	10:55	28.7		27.9	8.0	8.3			N.D.<0.8	3.9	N.D.<2.5	0.002	0.022	0.004						142	3.40*10 ⁴		0.16	7.1	>30	2.1						
瑪鍊溪	瑪鍊溪取水口	R21	甲	7/10	10:40	36.4		31.4	8.1	8.6		0.034	0.9	3.2	2.9	N.D.<0.0007	N.D.<0.013	N.D.<0.002						136	1.90*10 ³		0.09	10.1	>30	3.7			11.0			
瑪鍊溪	裕大橋	R22	甲	7/10	10:54	36.2		31.2	7.4	6.2		0.039	1.1	N.D.<3.1	6.8	N.D.<0.0007	0.066	N.D.<0.002						136	9.10*10 ²		0.05	11.0	>30	9.0			13.6			
瑪鍊溪	四十九號橋	R23	無	7/17	10:30	30.0		24.7	7.8	8.3		0.036	N.D.<0.8	N.D.<3.1	7.1	N.D.<0.0007	N.D.<0.013	N.D.<0.002						114	3.40*10 ³		0.02	13.6	>30	1.9			6.6			
瑪鍊溪	國中橋	R24	無	7/17	10:39	33.4		28.5	8.7	8.4			N.D.<0.8	N.D.<3.1	N.D.<2.5	N.D.<0.0007	N.D.<0.013	N.D.<0.002						135	2.00*10 ³		0.03	16.3	>30	3.6						
東勢格溪	東勢格溪取水口	R31	無	7/17	10:47	34.7		29.6	8.0	8.3			0.8	3.4	2.9	N.D.<0.0007	0.017	N.D.<0.002						168	3.00*10 ³		0.05	20.3	>30	3.8						
景美溪	石碇取水口	R32	無	7/23	10:32	25.4		19.5	7.9	8.5		0.038	N.D.<0.8	N.D.<3.1	N.D.<2.5	N.D.<0.0007	N.D.<0.013	N.D.<0.002						118	2.70*10 ³		0.02	9.8	>30	1.2			4.3			
基隆河	圓山取水口	R33	無	7/23	10:03	28.6		27.0	7.8	7.8			N.D.<0.8	N.D.<3.1	5.3	N.D.<0.0007	N.D.<0.013	N.D.<0.002						163	2.30*10 ³		0.05	15.7	>30	4.1						
基隆河	康誥坑溪取水口	R34	無	7/23	09:51	30.2		30.7	8.2	8.8			N.D.<0.8	3.3	4.4	N.D.<0.0007	N.D.<0.013	0.003						179	3.50*10 ³		0.05	19.9	>30	4.3						