

公開類
季報

期間終了一個月內編報

新北市 河川水質監測結果

中華民國102年10月

編製機關 新北市政府環境保護局

表號 1134-05-02-2

河川名稱	監測站名	監測站編號	水體分類等級	採樣日期	採樣時間	氣溫 ℃	水流量 CMS	水質紀錄										水質紀錄										備註							
								水溫 ℃	pH值	溶氧量 mg/L	總氮 mg/L	總磷 mg/L	生化需氧量 (5天20℃) mg/L	化學需氧量 mg/L	懸浮固體 mg/L	鎘	鉛	總銻	汞	銅	鋅	導電度 μmho/ cm/25℃	大腸桿菌 群 個/100mL	陰離子 表面活性劑 mg/L	氨氮 mg/L	氯鹽 mg/L	透視度 cm		濁度 NTU	六價 鉻 mg/L (第四位)	硫酸 鹽 mg/L	鐵 mg/L	錳 mg/L		
																																		mg/L(統計至小數第四位)	
水仙溪	靈山宮	R01	無	10/1	10:10	25.3		25.2	7.1	5.5			6.2	11.8	17.4									261	5.70*10 ³		3.65	19.2	>30	2.4					
水仙溪	小石板橋	R02	無	10/1	10:15	26.7		26.7	7.7	6.1			16.8	21.9	5.0									471	2.00*10 ⁴		17.7	31.8	>30	4.8					
林口溪	林口溪橋	R03	無	10/1	10:40	26.1		26.0	7.6	6.2			11.7	46.9	21.4									363	2.10*10 ⁴		6.48	31.3	>30	16					
林口溪	下福橋	R04	無	10/1	10:50	27.1		26.4	7.7	7.2			8.8	29.7	N.D.<25									420	7.70*10 ⁴		4.45	38.9	>30	9.3					
觀音坑溪	集福橋	R05	無	10/2	09:30	29.5		27.8	8.5	8.5			4.2	18.1	3.2									418	5.50*10 ⁴		2.03	34.7	>30	8.6					
觀音坑溪	觀音坑三號橋	R06	無	10/2	09:43	29.7		26.7	7.6	8.4			2.7	13.4	N.D.<2.5									375	2.50*10 ⁴		0.41	28.8	>30	7.3					
五股坑溪	洲子一橋	R07	無	10/2	10:00	29.7		27.3	7.6	5.8			16.2	40.6	13.5									416	4.10*10 ⁵		4.5	35.6	>30	11					
五股坑溪	俊成橋	R08	無	10/2	11:00	29.8		28.8	7.9	8.3			6.4	31.2	6.3									434	4.50*10 ⁵		4.37	40	>30	8.9					
大科坑溪	大窠橋	R09	無	10/2	10:28	29.5		27.7	7.8	7.4			7.3	24.9	24.5									1270	2.10*10 ⁵		16.9	241	>30	9.8					
大科坑溪	山脚溪橋	R10	無	10/2	10:45	28.9		28.0	7.9	8.4			5.1	15.1	8.2									1230	9.90*10 ⁴		17.1	250	>30	7					
新店溪	青潭堰取水口	R11	甲	10/15	09:45	23.9		23.0	6.8	8.7			0.048	N.D.<0.8	N.D.<3.1	13.5								86	1.00*10 ³		0.01	4.6	>30	20			10.2		
新店溪	直潭堰取水口	R12	甲	10/15	10:00	24.5		22.8	7.1	8.9			0.027	N.D.<0.8	N.D.<3.1	9.8								94	5.20*10 ²		N.D.<0.007	4.0	>30	16			10.4		
大漢溪	鳶山堰取水口	R13	乙	10/16	09:48	21.6		22.8	7.5	8.4			0.039	N.D.<0.8	N.D.<3.1	42								168	2.10*10 ⁴		0.04	2.5	10	80			37.8		
三峡河	三峡堰取水口	R14	無	10/16	10:14	20.5		21.5	7.4	8.9			0.026	N.D.<0.8	N.D.<3.1	N.D.<2.5								139	3.10*10 ³		N.D.<0.007	5.9	>30	2.0			17.4		
大豹溪	湊合橋	R17	無	10/16	10:25	20.7		21.1	7.4	8.8			N.D.<0.8	N.D.<3.1	N.D.<2.5									138	5.40*10 ³		N.D.<0.007	3.0	>30	1.5					
大豹溪	東眼橋	R18	無	10/16	10:37	22.9		21.3	7.6	8.5			N.D.<0.8	N.D.<3.1	N.D.<2.5									119	1.80*10 ³		N.D.<0.007	2.7	>30	1.6					
瑪鍊溪	瑪鍊溪取水口	R21	無	10/30	10:22	22.4		20.4	7.6	9.1			0.073	N.D.<0.8	N.D.<3.1	N.D.<2.5								111	1.90*10 ³		0.01	11.5	>30	1.8			8.6		
瑪鍊溪	裕大橋	R22	無	10/30	10:35	22.5		21.2	7.9	9.0			0.044	N.D.<0.8	N.D.<3.1	N.D.<2.5								134	4.50*10 ³		0.03	10.8	>30	1.6			10.4		
瑪鍊溪	四十九號橋	R23	無	10/30	10:02	24.0		21.6	7.5	9.1			N.D.<0.8	N.D.<3.1	N.D.<2.5									159	2.80*10 ⁴		0.06	14.0	>30	2.3					
瑪鍊溪	國中橋	R24	無	10/30	10:10	23.4		21.8	7.1	7.7			1.3	N.D.<3.1	N.D.<2.5									169	2.20*10 ⁴		0.22	15.1	>30	2					
東勢格溪	東勢格溪取水口	R31	無	10/31	10:25	21.8		19.8	7.5	9.0			0.024	N.D.<0.8	N.D.<3.1	N.D.<2.5								100	8.00*10 ²		0.01	8.2	>30	1.4			10.2		
景美溪	石碇取水口	R32	無	10/31	10:05	23.7		21.6	7	9.1			0.030	N.D.<0.8	3.3	N.D.<2.5								180	3.40*10 ³		0.02	12.2	>30	1.7			13.0		
基隆河	圓山取水口	R33	乙	10/29	09:55	24.5		20.4	8.1	9.2			0.020	N.D.<0.8	N.D.<3.1	N.D.<2.5								160	2.10*10 ²		0.02	12.0	>30	1.6			20.2		
基隆河	康誥坑溪取水口	R34	無	10/29	10:37	24.8		20.8	7.6	9.2			0.022	1.2	3.6	N.D.<2.5								115	2.90*10 ²		0.06	9.5	>30	0.80			10.2		