

臺北縣河川水質監測結果

中華民國 93年12月

河川名稱	監測站名	監測站編號	水體類等	採樣日期	採樣時間	氣溫 ℃	水流量 CMS	水質紀錄										水質紀錄										備註						
								水溫 ℃	pH值	溶氧量 mg/L	總氮 mg/L	總磷 mg/L	生化需氧量 (5天20℃) mg/L	化學需氧量 mg/L	懸浮固體 mg/L	鎘 mg/L	鉛 mg/L	總鉻 mg/L	汞 mg/L	銅 mg/L	鋅 mg/L	導電度 μmho/cm/25℃	大腸桿菌群 個/100ml	陰離子表面活性劑 mg/L	氨氮 mg/L	氯鹽 mg/L	透視度 cm		濁度 NTU	六價鉻 mg/L(統計至小數第四位)	硫酸鹽 mg/L			
																																mg/L(統計至小數第四位)		
水仙溪	靈山宮	R01	無	12/7	10:02	19.0		20.0	7.5	6.4			10	27	14										460	2.3*10 ⁵		16	34	>30	12			
水仙溪	小石板橋	R02	無	12/7	09:53	18.0		19.0	7.4	7.7			8.6	23	16										391	1.0*10 ⁵		10	37	>30	12			
林口溪	林口溪橋	R03	無	12/7	10:32	20.0		19.0	7.4	7.6			3.8	18	3.4										362	5.5*10 ³		7.0	37	>30	1.7			
林口溪	下福橋	R04	無	12/7	10:43	18.0		19.0	7.6	7.1			24	26	14										461	1.1*10 ⁵		7.9	47	>30	13			
觀音坑溪	集福橋	R05	無	12/8	11:07	17.0		18.0	6.1	8.1			12	357	11										578	2.2*10 ⁵		7.7	65	>30	11			
觀音坑溪	觀音坑三號橋	R06	無	12/8	11:17	17.0		18.0	8.0	8.3			2.9	118	20										496	6.1*10 ³		4.7	42	>30	20			
五股坑溪	洲子一橋	R07	無	12/8	10:45	17.0		19.6	7.8	3.5			32	130	40										1130	5.7*10 ⁴		7.1	37	14.2	29			
五股坑溪	俊成橋	R08	無	12/8	10:31	17.8		19.0	7.4	6.0			35	173	14										479	9.7*10 ⁴		3.8	46	19.6	21			
大科坑溪	大窠橋	R09	無	12/8	10:18	17.5		19.3	7.6	6.6			27	147	30										736	3.4*10 ⁵		6.6	97	12.4	23			
大科坑溪	山腳溪橋	R10	無	12/8	10:10	18.0		19.0	7.7	7.3			16	101	16										741	8.7*10 ⁴		4.3	83	19.2	18			
新店溪	青潭堰取水口	R11	甲	12/15	11:00	21.0		18.5	7.5	9.5		0.08	<0.7	6.6	5.4										116	2.4*10 ³		0.04	6.4	>30	8.1			18
新店溪	直潭堰取水口	R12	甲	12/15	10:35	21.0		19.5	7.3	9.8		0.02	<0.7	7.7	17										83	2.2*10 ³		0.03	6.4	17.2	31			13
大漢溪	嵩山堰取水口	R13	乙	12/14	09:57	18.5		17.8	7.9	9.0		0.15	<0.7	14	157										183	1.7*10 ³		0.07	7.9	3.0	220			38
三峽河	三峽堰取水口	R14	無	12/14	10:18	20.0		17.3	7.8	9.2		0.02	<0.7	<4.0	<2.0										248	8.5*10 ²		0.06	7.5	>30	0.75			23
大豹溪	湊合橋	R17	無	12/14	10:33	20.0		17.0	7.8	8.8			<0.7	<4.0	<2.0										135	1.2*10 ⁴		0.04	7.6	>30	0.55			
大豹溪	東眼橋	R18	無	12/14	10:51	24.0		18.1	7.5	8.9			<0.7	<4.0	<2.0										129	3.8*10 ²		0.03	7.3	>30	0.60			
瑪鍊溪	瑪鍊溪取水口	R21	無	12/22	13:15	20.8		20.2	7.6	8.1		0.03	<0.7	9.4	2.4	<0.001	<0.01	<0.02		<0.002					139	4.4*10 ²		0.05	10	>30	2.2			9.5
瑪鍊溪	裕大橋	R22	無	12/22	13:02	21.4		19.2	7.6	8.4		0.03	<0.7	9.9	<2.0	<0.001	<0.01	<0.02		<0.002					98	5.3*10 ²		0.01	10	>30	2.8			5.4
瑪鍊溪	四十九號橋	R23	無	12/22	12:47	20.0		21.1	7.6	8.6			<0.7	5.9	3.2	<0.001	<0.01	<0.02		<0.002					145	3.9*10 ³		0.04	18	>30	3.0			
瑪鍊溪	國中橋	R24	無	12/22	12:38	23.0		21.2	7.5	6.6			1.1	24	2.6	<0.001	<0.01	<0.02		<0.002					154	1.4*10 ⁴		0.12	14	>30	2.0			
百拉卡溪	百拉卡取水口	R28	無	12/22	10:25	16.1		17.2	7.8	7.2		0.03	<0.7	4.1	<2.0	<0.001	<0.01	<0.02		<0.002						5.4*10 ²		0.04	6.4	>30	2.3			5.4
東勢格溪	東勢格溪取水口	R31	無	12/21	10:46	18.5		18.0	8.0	8.9		<0.02	<0.7	<4.0	10	<0.001	<0.01	<0.02		<0.002					102	1.2*10 ³		0.06	14	>30	1.6			11
景美溪	石碇取水口	R32	無	12/21	11:17	20.1		18.7	8.3	9.0		0.03	<0.7	13	8.3	<0.001	<0.01	<0.02		<0.002					182	6.5*10 ³		0.02	15	>30	1.8			18
基隆河	圓山取水口	R33	乙	12/28	13:21	18.4		17.9	7.3	9.0		<0.02	<0.7	<4.0	18	<0.001	<0.01	<0.02		<0.002					91	2.5*10 ³		0.01	15	>30	1.6			8.9
基隆河	香諾坑取水口	R34	無	12/28	10:18	19.3		18.7	7.7	8.4		<0.02	<0.7	<4.0	8.7	<0.001	<0.01	<0.02		<0.002					81	2.3*10 ³		0.01	9.6	>30	5.1			10