

臺北縣河川水質監測結果

中華民國97年06月

河川名稱	監測站名	監測站編號	水體分類等級	採樣日期	採樣時間	氣溫 ℃	水流量 CMS	水質紀錄										水質紀錄										備註							
								水溫 ℃	pH值	溶氧量 mg/L	總氮 mg/L	總磷 mg/L	生化需氧量 (5天20℃) mg/L	化學需氧量 mg/L	懸浮固體 mg/L	鎘	鉛	總鉻	汞	銅	鋅	導電度 μmho/ cm/25℃	大腸桿菌群 個/100ml	陰離子表面活性劑 mg/L	氨氮 mg/L	氯鹽 mg/L	透視度 cm		濁度 NTU	六價鉻 mg/L (第四位)	硫酸鹽 mg/L	鐵 mg/L	錳 mg/L		
																																		mg/L(統計至小數第四位)	
水仙溪	靈山宮	R01	無	6/3	09:53	27.1		23.8	7.2	7.2			8.6	32	17									240	4.60*105		6.7	16	>30	14					
水仙溪	小石板橋	R02	無	6/3	09:47	27.2		23.7	7.1	7.0			12	30	18									210	4.20*105		5.7	17	23	18					
林口溪	林口溪橋	R03	無	6/3	10:23	25.4		23.1	6.9	7.1			7.1	24	19									197	2.60*104		2.9	18	24.5	21					
林口溪	下福橋	R04	無	6/3	10:34	25.1		23.3	6.8	7.2			8.4	23	26									202	5.90*104		1.6	18	22.4	31					
觀音坑溪	集福橋	R05	無	6/4	09:40	24.1		22.8	6.2	8.0			5.9	19	30									362	8.50*104		2.4	40	15	45					
觀音坑溪	觀音坑三號橋	R06	無	6/4	09:25	23.4		22.7	6.7	6.5			2.1	14	99									273	7.60*104		0.46	23	5.0	140					
五股坑溪	洲子一橋	R07	無	6/4	10:00	24.6		23.1	6.6	6.6			8.4	28	8.6									301	2.80*105		2.4	22	>30	10					
五股坑溪	俊成橋	R08	無	6/4	10:15	24.6		23.0	6.5	8.0			4.6	23	6.7									274	4.50*104		1.4	22	>30	6.1					
大科坑溪	大窠橋	R09	無	6/4	10:20	24.7		24.0	6.8	7.7			10	33	8.7									479	2.10*105		4.2	60	>30	7.5					
大科坑溪	山腳溪橋	R10	無	6/4	10:30	25.3		24.4	7.0	7.7			12	30	6.4									496	8.10*104		2.9	59	>30	7.1					
新店溪	青潭堰取水口	R11	甲	6/10	09:50	26.0		22.4	7.4	8.7			0.01	N.D.<0.7	N.D.<3.0	2.9								90	2.40*103		N.D.<0.0	7.0	>30	3.6			11		
新店溪	直潭堰取水口	R12	甲	6/10	10:10	28.0		24.0	7.5	8.3			0.06	N.D.<0.7	N.D.<3.0	N.D.<2.5								105	3.40*102		N.D.<0.0	4.0	>30	1.1			14		
大漢溪	鳶山堰取水口	R13	乙	6/17	09:54	26.3		22.6	6.5	7.0			0.16	3.2	8.6	206								139	3.20*104		0.14	6.1	3.0	370			18		
三峽河	三峽堰取水口	R14	無	6/17	10:20	28.7		23.4	6.1	8.9			0.04	N.D.<0.7	N.D.<3.0	11								100	5.30*103		N.D.<0.00	5.2	>30	14			11		
大豹溪	湊合橋	R17	無	6/17	10:32	28.0		23.4	6.1	8.6				N.D.<0.7	N.D.<3.0	12	0.003	0.02	0.004					101	4.40*103		N.D.<0.00	4.2	>30	19			0.15	0.01	
大豹溪	東眼橋	R18	無	6/17	10:43	29.4		23.3	6.0	8.7				N.D.<0.7	N.D.<3.0	6.9	0.002	0.02	0.004					81	3.20*103		N.D.<0.00	3.5	>30	9.5			0.16	0.01	
瑪鍊溪	瑪鍊溪取水口	R21	無	6/11	10:48	29.1		25.7	8.0	8.5			0.04	N.D.<0.7	N.D.<3.0	9.1	N.D.<0.0007	N.D.<0.01	N.D.<0.002					135	5.20*103		0.02	11	>30	7.0			11	0.16	0.03
瑪鍊溪	裕大橋	R22	無	6/11	10:22	27.6		25.1	8.1	8.8			0.04	1.2	3.1	5.1	N.D.<0.0007	N.D.<0.01	N.D.<0.002					100	2.30*103		N.D.<0.00	11	>30	4.2			6.5	0.1	0.007
瑪鍊溪	四十九號橋	R23	無	6/11	10:00	27.5		25.0	8.0	8.6				0.8	3.6	19	N.D.<0.0007	N.D.<0.01	N.D.<0.002					143	1.80*104		0.04	14	>30	23			0.19	0.02	
瑪鍊溪	國中橋	R24	無	6/11	10:08	28.4		24.6	7.6	8.4				1.0	4.8	23	N.D.<0.0007	N.D.<0.01	N.D.<0.002					845	7.40*104		0.25	202	>30	9.7			0.3	0.05	
東勢格溪	東勢格溪取水口	R31	無	6/18	09:45	30.0		25.7	7.4	8.5			0.02	N.D.<0.7	N.D.<3.0	N.D.<2.5	0.002	0.02	0.003					81	7.30*102		N.D.<0.00	8.9	>30	1.7			11	0.12	0.005
景美溪	石碇取水口	R32	無	6/18	10:16	30.4		26.0	7.5	8.4			0.005	0.7	3.2	6.8	0.002	0.02	0.003					107	9.90*103		N.D.<0.00	7.3	>30	9.0			8.0	0.14	0.01
基隆河	圓山取水口	R33	乙	6/24	10:47	33.2		30.1	6.3	7.8			0.004	N.D.<0.7	N.D.<3.0	3.1	0.002	0.02	0.003					137	1.70*102		N.D.<0.00	9.7	>30	1.7			7.9	0.11	0.003
基隆河	康誥坑溪取水口	R34	無	6/24	09:52	31.9		27.4	6.3	8.3			0.07	N.D.<0.7	N.D.<3.0	11	0.002	0.02	0.003					112	1.30*103		N.D.<0.00	9.5	>30	2.6			12	0.08	0.004