

公開類

季報 期間終了一個月內編報

編製機關 臺北縣政府環境保護局

表號 1134-05-02-2

臺北縣河川水質監測結果

中華民國98年10月

河川名稱	監測站名	監測站編號	水體分類等級	採樣日期	採樣時間	氣溫 ℃	水流量 CMS	水質紀錄										水質紀錄										備註						
								水溫 ℃	pH值	溶氧量 mg/L	總氮 mg/L	總磷 mg/L	生化需氧量 (5天20℃) mg/L	化學需氧量 mg/L	懸浮固體 mg/L	鎘	鉛	總鉻	汞	銅	鋅	導電度 μmho/cm/25℃	大腸桿菌 個/100mL	陰離子 界面 活性劑 mg/L	氨氮 mg/L	氯鹽 mg/L	透視度 cm		濁度 NTU	六價鉻 mg/L (統計至小數第四位)	硫酸鹽 mg/L	鐵 mg/L	錳 mg/L	
																																		mg/L(統計至小數第四位)
水仙溪	靈山宮	R01	無	10/6	09:00	22.1		22.7	6.7	7.6			5.0	11.6	4.6								252	3.80*104		2.02	15.7	>30	3.8					
水仙溪	小石板橋	R02	無	10/6	09:20	22.0		23.1	6.7	6.8			5.4	12.8	8.4								258	1.40*106		3.14	17.9	>30	6.3					
林口溪	林口溪橋	R03	無	10/6	09:40	22.0		21.4	7.0	7.3			4.1	16.8	8.6								279	1.60*104		1.52	22.5	>30	7.4					
林口溪	下福橋	R04	無	10/6	09:55	22.0		22.7	7.1	7.8			4.4	17.0	11.3								305	1.80*104		0.69	26.4	>30	11					
觀音坑溪	集福橋	R05	無	10/7	09:30	25.5		24.0	6.8	8.4			3.7	12.0	4.7								610	1.60*104		1.19	66.0	>30	5.0					
觀音坑溪	觀音坑三號橋	R06	無	10/7	09:35	24.5		23.1	6.7	8.4			2.5	8.5	6.8								331	1.70*104		0.21	33.0	>30	12					
五股坑溪	洲子一橋	R07	無	10/7	09:43	22.5		23.2	6.8	6.4			11.0	28.0	9.3								399	2.40*105		5.32	30.0	>30	6.6					
五股坑溪	復成橋	R08	無	10/7	10:00	22.6		23.2	6.7	7.6			10.0	31.9	10.8								410	3.10*105		6.90	30.4	>30	7.2					
大科坑溪	大窠橋	R09	無	10/7	10:15	22.5		22.8	7.0	8.5			5.4	20.0	7.3								703	5.00*105		4.56	102	>30	4.7					
大科坑溪	山脚溪橋	R10	無	10/7	10:25	22.0		22.6	7.2	5.6			18.9	49.2	10.1								889	2.50*105		3.82	90.7	>30	6.8					
新店溪	青潭堰取水口	R11	甲	10/13	09:20	26.2		22.6	7.0	9.1			0.146	N.D.<0.6	8.0	312							72	4.30*103		0.02	4.6	1.0	260			15		
新店溪	直潭堰取水口	R12	甲	10/13	09:40	26.0		22.4	6.7	9.4			0.231	N.D.<0.6	8.5	216							73	1.20*103		0.03	3.5	2.0	220			13		
大漢溪	鳶山堰取水口	R13	乙	10/12	10:00	24.8		23.5	6.7	8.4			0.092	0.8	5.5	65.2							187	6.00*104		0.07	1.6	4.0	100			33		
三峽河	三峽堰取水口	R14	無	10/12	10:17	23.0		22.1	7.2	9.3			0.018	N.D.<0.6	4.3	N.D.<2.5							83	6.60*103		0.02	2.6	>30	3.6			10		
大豹溪	湊合橋	R17	無	10/12	10:40	23.8		22.5	6.6	9.2			N.D.<0.6	5.5	6.7								81	6.20*103		0.01	2.2	>30	7.9					
大豹溪	東眼橋	R18	無	10/12	10:45	23.0		22.0	6.8	8.9			N.D.<0.6	5.0	4.0								71	3.50*103		0.01	2.4	>30	3.7					
瑪鍊溪	瑪鍊溪取水口	R21	無	10/20	10:10	23.2		21.4	6.6	9.4			0.036	N.D.<0.6	N.D.<3.6	2.7							119	1.00*104		0.03	10.9	>30	3.9			9.0		
瑪鍊溪	裕大橋	R22	無	10/20	10:00	24.7		21.9	6.4	8.8			0.018	0.8	N.D.<3.6	N.D.<2.5							95	2.10*103		N.D.<0.004	9.3	>30	0.70			6.3		
瑪鍊溪	四十九號橋	R23	無	10/20	09:50	24.8		22.4	6.2	8.1			0.7	N.D.<3.6	3.1								136	3.60*104		0.02	10.2	>30	2.8					
瑪鍊溪	國中橋	R24	無	10/20	10:20	22.8		22.0	6.6	8.7			0.9	N.D.<3.6	N.D.<2.5								139	7.60*103		0.05	11.8	>30	2.5					
東勢格溪	東勢格溪取水口	R31	無	10/21	10:31	20.9		21.1	6.9	9.4			0.029	N.D.<0.6	4.1	6.2							99	N.D.<10		0.02	8.3	>30	3.6			10		
景美溪	石碇取水口	R32	無	10/21	09:55	26.3		22.9	7.0	9.1			0.085	1.1	N.D.<3.6	N.D.<2.5							163	4.40*103		0.03	6.1	>30	1.6			14		
基隆河	圓山取水口	R33	乙	10/27	10:37	22.5		22.2	6.5	7.8			0.050	1.0	N.D.<3.6	16.3							124	1.80*103		N.D.<0.004	11.0	>30	9.2			16		
基隆河	康誥坑溪取水口	R34	無	10/27	09:50	23.2		21.5	6.5	6.8			0.017	1.0	N.D.<3.6	3.8							100	2.60*103		0.008	9.4	>30	1.5			10		

臺北縣政府

